

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2022

Submitted Date:

08/08/2022

Document Number:

688312833

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10646
Name of Operator: AXIS EXPLORATION LLC
Address: 370 17TH ST SUITE 5200
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Quint, Craig		craig.quint@state.co.us	
Civitas		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204395	WELL	TA	04/01/2020	DSPW	005-06480	REEVES 32-21 4	TA

General Comment:

Routine UIC Inspection, passed

Form: (04)403064433 6/2/2022 This well is designated inactive and must be properly returned to production, plugged and abandoned, have an approved Form 5B or be submitted on a Form 6A (to be designated as Out of Service) no later than no later than November 1, 2022.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	720-340-5540		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Other	# 1				
Comment:	well had LO/TO				
Corrective Action:		Date:			
Type: Bradenhead	# 1				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 204395 Type: WELL API Number: 005-06480 Status: TA Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 700 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND
 TC: Pressure or inches of Hg 0 Previous Test Pressure _____ Last MIT: 04/16/2018
 Brhd: Pressure or inches of Hg SBDI Previous Test Pressure _____ AnnMTReq: _____

Comment: 7/14/2 Tubing was at 700 psi. Recommend blowing down the tubing and verifying if it comes back. Tubing was 0 psi at this time. A trailer park is location ~3000' east of well. Per DB/COGCC Engineer on 1/19/2021, "Isolation is not within 100' of perforations - reset or variance in front of restoring as IJ well." Per wellbore diagram-packer at 6940', perfs at 7736-7372'.
 Verify if flowline was removed during tank battery decommissioning because there is a small area of subsidence east

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA since 11/1/2019 on scout card.
 Document #403064433 04 (OBJ-TA) -00 TA date: 10/14/2019 Attachment count: 2 APPROVED 6/2/2022 6/1/2022
 Form: (04)403064433 6/2/2022 This well is designated inactive and must be properly returned to production, plugged and abandoned, have an approved Form 5B or be submitted on a Form 6A (to be designated as Out of Service) no later than no later than November 1, 2022.

Corrective Action: Form: (04)403064433 6/2/2022 This well is designated inactive and must be properly returned to production, plugged and abandoned, have an approved Form 5B or be submitted on a Form 6A (to be designated as Out of Service) no later than no later than November 1, 2022.
 Contact COGCC Engineering.
 Date: 11/01/2022

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403129155	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5823321
688312844	Axis Reeves 32-21 4	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5823318