

**Inspection Photos**  
**Location Name: Spike St GWS CC 30-14**  
**API #05-123-15829**



**Photo #1 Well & debris**

**Photo #2 Debris**