

Inspection Photos

ID: 412295

Operator: RENCO GAS PIPELINE INC

Inspection Date: 8/11/2022



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest at the abandoned facility. The tank has been removed since previous inspection. No reclamation has been performed and there is some debris and gravel shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

412295 | Date: 8/11/2022

Inspection Photos




Photo 2. There is a flowline riser which is on an active line shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

412295 | Date: 8/11/2022

Inspection Photos



Photo 3. The abandoned engine compresor has been removed since the previous inspection. This area has not been reclaimed and consists of weeds and bare soil.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

412295 | Date: 8/11/2022

Inspection Photos



Photo 4. There is a pile of hardened oily waste that remains shown at red arrow. A t-post remains at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

412295 | Date: 8/11/2022

Inspection Photos



Photo 5. Facing toward the surrounding undisturbed pasture that consists of native Blue grama grassland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

412295 | Date: 8/11/2022