

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 201810 Type: WELL API Number: 001-07214 Status: SI Insp. Status: SI

Workover

Comment: At time of inspection well was in process of P&A. At time of inspection rig crew had just squeezed at approx 3000' MD, and cleaning out pump lines. Compnay representative infomred me that he was waiting for instruction from Civitas engineering for next step of P&A process for specific well.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were overcast, raining, cool.	medinaj	08/16/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504154	Inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5831631