

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/16/2022

Submitted Date:

08/16/2022

Document Number:

699504157

**FIELD INSPECTION FORM**Loc ID 449179 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449177	WELL	PR	11/23/2018	OW	001-10004	Bear 3-65 22-23 3AH	PR
449178	WELL	PR	11/16/2018	OW	001-10005	BEAR 3-65 22-23 3DH	PR
454546	WELL	PR	11/21/2018	OW	001-10150	Bear 3-65 22-23 3CH	PR
454547	WELL	PR	11/09/2018	OW	001-10151	Bear 3-65 22-23 3BH	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type LOCATION

Comment: 4' barb wire

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Compressor

# 1

Comment: Gas Lift

Corrective Action:

Date:

Type: Gas Meter Run

# 2

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 5

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 4

Comment:

Corrective Action:

Date:

Type: VRT

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: electric / automation

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

# 6

Comment:

Corrective Action:		Date:	
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	7	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--

**Inspected Facilities**

Facility ID: 449177	Type: WELL	API Number: 001-10004	Status: PR	Insp. Status: PR
Facility ID: 449178	Type: WELL	API Number: 001-10005	Status: PR	Insp. Status: PR
Facility ID: 454546	Type: WELL	API Number: 001-10150	Status: PR	Insp. Status: PR
Facility ID: 454547	Type: WELL	API Number: 001-10151	Status: PR	Insp. Status: PR

**Producing Well**

Comment: PR	
Corrective Action:	Date:

**BradenHead**

Date of Last Brhd Test: 07/15/2021	Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0
	Fluid Type:
	End Surf Csg Pressure: 0
Comment:	
Corrective Action:	Date:

**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were overcast, raining, cool.	medinaj	08/16/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504158	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5831633">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5831633</a>