

Inspection Photos

API: 05-071-07968

Operator: PRESCO INC

Inspection Date: 8/15/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/15/2022

Inspection Photos



Photo 1. Facing east along the former access road. The pre-existing road is stabilized with perennial vegetation. A culvert is installed at the drainage crossing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/15/2022

Inspection Photos



Photo 2. Facing southeast along the former access road. The road is stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/15/2022

Inspection Photos



Photo 3. Facing northeast along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/15/2022

Inspection Photos



Photo 4. Facing northeast toward the location. Perennial vegetation has established throughout the location and reflects reference area levels consisting of Western wheatgrass, Sand dropseed, Blue grama, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/15/2022

Inspection Photos



Photo 5. Facing north at the location. Perennial vegetation has established throughout the location and reflects reference area levels consisting of Western wheatgrass, Sand dropseed, Blue grama, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07968 | Date: 8/15/2022