

Inspection Photos

API: 05-071-07956

Operator: PRESCO INC

Inspection Date: 8/15/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 1. There is an erosional gully along the access road that was not repaired at Lat/Long:37.02219,-104.48216. Arrow points to 4.5 ft shovel.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 2. Facing northeast along the access road. The roadside was seeded in this area and vegetation is progressing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 3. Facing northeast along the access road. There is vegetation establishing along the road side and rock check dams are installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 4. Facing northeast further along the access road. There is vegetation establishing along the road side and rock check dams are installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 5. There are culverts installed along the road which has improved stormwater drainage. Culverts appear to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 6. The culvert inlets are maintained and clear of debris and sediment.



Photo 7. The culvert outlets have rock rip/rap outlet protection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 8. Facing northeast further along the access road. There is vegetation establishing along the road side and rock check dams are installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 9. Facing northeast further along the access road. Some of the rock check dams are in need of maintenance. The road side along this area has not established vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 10. Facing northeast further along the access road. There is vegetation establishing along the road side and rock check dams are installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 11. Facing northeast further along the access road. There is vegetation establishing along the road side and rock check dams are installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 12. Facing northeast further along the access road. There is vegetation establishing along the road side and rock check dams are installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 13. Facing southeast toward the location. The perennial vegetation establishment is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 14. Facing east at the location. The perennial vegetation establishment is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 15. Facing east at the northeast side of the location. The perennial vegetation establishment is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022

Inspection Photos



Photo 16. Facing southeast at the location. The perennial vegetation establishment is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07956 | Date: 8/15/2022