

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES-67S93W /13SESW

Location ID: 334677



Photo #7481 from entrance to location.



Photo #7482 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES-67S93W /13SESW

Location ID: 334677



Photo #7483 Undesirable plant species on location.



Photo #7484 Undesirable plant species on location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES-67S93W /13SESW

Location ID: 334677



Photo #7485 Heating insulation open ended and not capped.