

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES-67S93W /13SESW

Location ID: 334593



Photo #7487 from entrance to location.



Photo #7488 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES-67S93W /13SESW

Location ID: 334593



Photo #7489 from entrance to location.



Photo #7490 Multiple places with undesirable plant species on location.


## Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES-67S93W /13SESW

Location ID: 334593



**Photo #7491 Multiple places with undesirable plant species on location.**



**Photo #7492 Flow line heating insulation open ended and not capped.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES-67S93W /13SESW

Location ID: 334593



**Photo #7493 Flow line heating insulation open ended and not capped.**