

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES-67S93W /13NESE

Location ID: 334558



Photo #7494 from entrance to location.



Photo #7495 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES-67S93W /13NESE

Location ID: 334558



Photo #7496 Wireline.



Photo #7498 Workover rig.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES-67S93W /13NESE

Location ID: 334558



Photo #7500 Cement pump.



Photo #7502 Flat tank.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ROLES-67S93W /13NESE

Location ID: 334558



Photo #7505 Undesirable plant species.



Photo #7499 Undesirable plant species.