

Inspection Photos
Location Name: Huber-Rhoades 4-33
Location ID: 326516



IMG 01
Well sign




IMG 02
Location overview



IMG 03

Rig anchor not secured properly



IMG 04

Lube oil has begun to impact surface material



IMG 05

Stomwater channel has begun to form

IMG 06