

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2022

Submitted Date:

08/22/2022

Document Number:

702500321**FIELD INSPECTION FORM**Loc ID 325501 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214901	WELL	PR	03/22/1988	CBM	067-06505	SHOEMAKER 01-34 1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	PVC pipe near location entrance is debris or unused equipment (IMG 03).		
Corrective Action:	Remove debris or unused equipment per rule 606.		Date: 09/06/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Produced water tank and separator are enclosed by chain link fence. Compressor trailer is enclosed by sound panels.		
Corrective Action:			Date:

**Equipment:**

			corrective date
Type: Flow Line	# 3		
Comment:	4" line from wellhead to separator, line from separator to produced water tank, 2" line from gas meter run to off location.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electric panels		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	Compressor trailer located within sound panels.		
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:	Produced water tank and separator vent stack are screened properly.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:	Dehydrator inside housing unit within secondary containment.		
Corrective Action:			Date:

Type: Gas Meter Run	# 1	
Comment:	Gas meter calibration is within the last year.	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		37.255964,-107.728797
Comment:	2 above ground storage tanks, 300 bbl capacity each.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)	cone top	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 214901	Type: WELL	API Number: 067-06505	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					
Rip Rap	Pass					
		Compaction	Pass			
Ditches	Pass					
		Gravel	Pass			
Compaction	Pass					
Gravel	Pass					

Comment: Wattles on northwest corner are deteriorated and filled with sediment (IMG 04 and 05). Facilities must be operated in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Corrective Action: Repair/modify required BMPs per Rule 1002.f.(2)C

Date: 09/06/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500322	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5837041">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5837041</a>