

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2022

Submitted Date:

08/22/2022

Document Number:

702500327**FIELD INSPECTION FORM**Loc ID 326297 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216188	WELL	PR	03/16/1993	CBM	067-07794	HUBER-LEWIS 2-33	PR
455098	GAS COMPRESSOR STATION	AC	05/23/2018		-	HUBER-LEWIS 02-33 FC - CDP	AC

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location				
Lease Road:				
Type	Access			
comment:	Access road beginning to develop ruts.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Produced water tank capacity is not legible. (IMG 05).			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 09/06/2022
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused steel mesh near gas powered generator (IMG 03) and exhaust muffler near compressor skid (IMG 04) are unused equipment.			
Corrective Action:	Use or remove unused equipment per rule 606.			Date: 09/06/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Pump jack enclosed by stock panel.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Compressor skid enclosed by stock panel.			
Corrective Action:				Date:
Equipment:				
Type: Bird Protectors	# 1			corrective date
Comment:	Separator vent stack is screened properly.			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Telemetry			
Corrective Action:				Date:
Type: Compressor	# 1			
Comment:	Compressor skid.			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 11		
Comment:	3" line from wellhead to separator, 2" gas line from separator to compressor, 1" line from separator to gas powered prime mover, 3" line from off location to water discharge line at separator, 4" water line from off location, 3" gas line from off location to gas discharge line at separator, 4" line from separator to produced water, 2" gas line from separator to off location, 3" gas line at separator, 3" water in line at separator. Not in use: 1" line from separator to wellhead is locked out/tagged out.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas powered		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV STEEL		37.253401,-107.747901
Comment:	Partially buried produced water tank with steel mesh top.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	216188	Type:	WELL	API Number:	067-07794	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	455098	Type:	GAS	API Number:	-	Status:	AC	Insp. Status:	AC

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass					
Ditches	Pass					
		Culverts	Pass			
				Material Handling And Spill Prevention	Pass	
Berms	Pass					
Compaction	Pass					
		Compaction	Pass			
		Gravel	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500328	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5837044