

Interim Reclamation and Stormwater Inspection

August 9, 2022

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 459907

Inspection Document #: 697504114

Adams County, CO

SWNW Section 21 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates a ditch BMP along the perimeter of location. Operator should consider stabilizing the ditch BMP to reduce the velocity of stormwater.



Photo 2. Photo taken from the entrance of location, facing West. Photo illustrates Operator has installed an additional BMP- sediment trap with a stabilized outlet.

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 3. Photo taken of the stabilized outlet on the previous photo.




Photo 4. Photo taken from the entrance of location. Operator does not have the required paperwork per Rule 406.c.



Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 5. Photo taken from the entrance of location, facing East. Photo illustrates the cut slopes have been seeded and desirable vegetation is establishing to provide long term stabilization.



Photo 6. Photo taken from the entrance of location, facing North. Photo illustrates a fence has been installed around the entire location.

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 7. Photo taken from the entrance of location, facing West. See comments under Photo 6. Also, Operator has added recycled asphalt along the entire length of the access road to stabilize it and control erosion.



Photo 8. Photo taken from the southern location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 9. Photo taken from the northeastern well pad, facing North. Operator has installed a stabilized riprap channel.



Photo 10. Photo taken from the previous photo illustrates trash within the disturbance area of the location.

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 11. Photo taken from the northern facility pad, facing South. Photo illustrates the current BMPs appear to be in proper functioning condition.



Photo 12. Photo taken from the previous photo illustrates the stabilized outlet of the sediment trap.

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 13. Photo taken from the entrance of location, facing South. Photo illustrates debris/trash.



Photo 14. Photo taken along a portion of the main access road, facing North. See comments under Photo 7.