

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2022

Submitted Date:

08/24/2022

Document Number:

702500340

FIELD INSPECTION FORMLoc ID 325730 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------------|--------------------------|
| , General | | sjninspections@ikavenergy.com | All SW field inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 215301 | WELL | PR | 09/26/2000 | CBM | 067-06906 | CLOVIS B 1 | PR |

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|-----------------------------------------------------------------------------|-------|--|
| Type | WEEDS | | |
| Comment: | Weeds beginning to become established along perimeter of location (IMG 04). | | |
| Corrective Action: | | Date: | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment near wellhead (IMG 03). | | |
| Corrective Action: | | Date: | |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|----------------------------------------------------------------------------|-------|--|
| Type | OTHER | | |
| Comment: | Wellhead, electric panels, and produced water are enclosed by stock panel. | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Location enclosed by wire fence. | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------------|---------------------------------------------------------------------------------------------------------------------------|-------|-----------------|
| Type: Bird Protectors | # 1 | | corrective date |
| Comment: | Separator vent stack is screened properly | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 3 | | |
| Comment: | 3" line from wellhead to separator, line from separator to produced water, 4" line from gas meter run to off location. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 6 | | |
| Comment: | Telemetry, Valve cluster pit, cathodic protection, corrosion inhibitor, pump control panel, electric cabinet and shut off | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 1 | | |

| | | | |
|---------------------|------------------------------------------------|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Linear rod pump | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Gas meter calibration is within the last year. | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead is accessible. | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---------------------------------------|----------|-----------|---------|-----------------------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | <50 BBLS | PBV STEEL | | 37.119007,-107.857455 | |
| Comment: | Partially buried produced water tank. | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 21 bbl | |
| Other (Type) | cone top | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | |
|----------------------|------------|-----------------------|------------|------------------|
| Facility ID: 215301 | Type: WELL | API Number: 067-06906 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|----------------------------------------|--------------------------|---------|
| | | | | Material Handling And Spill Prevention | Pass | |
| | | Compaction | Pass | | | |
| Compaction | Pass | | | | | |
| | | Gravel | Pass | | | |
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 702500341 | Photo doc | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5839351 |