

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403100537

Date Received:

07/11/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

.General

FarmingtonRegulatoryTechs@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500162

Inspection Date: 07/01/2022

FIR Submit Date: 07/05/2022

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326530

Location Name: HUBER-CROOK-N35N8W Number: 26SWNE County: LA PLATA

Qtrqr: SWNE Sec: 26 Twp: 35N Range: 8W Meridian: N

Latitude: 37.276930 Longitude: -107.710260

FACILITY - API Number: 05-067- -00 Facility ID: 89148

Facility Name: HUBER-CROOK Number: 4-26

Qtrqr: SWNE Sec: 26 Twp: 35N Range: 8W Meridian: N

Latitude: 37.276930 Longitude: -107.710260

CORRECTIVE ACTIONS:

1 ☒ CA# 163062

Corrective Action: Use or remove equipment per rule 606.

Date: 07/19/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: Unused equipment and trash around the pump jack and location was removed. See attached photos.

COGCC Decision: Approved

COGCC Representative: CA from previous inspection Doc# 702500162 has been satisfactorily completed.

2 ☒ CA# 163063

Corrective Action: Remove trash per rule 606.

Date: 07/13/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: Unused equipment and trash around the pump jack and location was removed. See attached photos.

COGCC Decision: Approved

COGCC Representative: CA from previous inspection Doc# 702500162 has been satisfactorily completed.

3 ☒ CA# 163064

Corrective Action: Remove oily residue on floor, remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 07/19/2022

Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: All residue in the meter house floor and impacted soil was removed and dispose of. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500162 has been satisfactorily completed.

4 ☒ CA# 163065

Corrective Action: Install proper guy line markers per Rule 1003.a

Date: 07/19/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: . Installed rig anchor marked and hooked up the muffler. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500162 has been satisfactorily completed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: OperationsRegulatory Tech

Date: 7/11/2022 6:11:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403100537	FIR RESOLUTION SUBMITTED
403100539	Huber-Crook 4-26_Resolved Photos

Total Attach: 2 Files