

Construction and Stormwater Inspection

August 10, 2022

Operator: NOBLE ENERGY INC- #100322

Location ID: 460265

Inspection Document #: 697504120

Weld County, CO

NWNE Section 31 T4N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name:CC31-02 /Pad
Location ID: 460265



Photo 1. Photo taken from the west entrance of location, facing North. Photo illustrates a cattle guard which would also serve as a VTC device BMP.



Photo 2. Photo taken from the northwestern location, facing South. Photo illustrates a sediment basin with evidence of stormwater repairs.

Inspection Photos
Location Name:CC31-02 /Pad
Location ID: 460265



Photo 3. Photo taken from the western location, facing South. Photo illustrates the stabilized outlet of the sediment basin which appears to be in proper functioning condition.



Photo 4. Photo taken along a portion of the western location. Photo illustrates how the filtrex wattle properly worked to keep sediment from leaving location.

Inspection Photos
Location Name:CC31-02 /Pad
Location ID: 460265



08.10.2022 11:52

Photo 5. Photo taken from the southwestern location, facing North. See comments under Photo 2.



08.10.2022 11:53

Photo 6. Photo taken from the southwestern location, facing South. Photo illustrates stormwater repairs are in process and in need of maintenance.

Inspection Photos
Location Name:CC31-02 /Pad
Location ID: 460265



Photo 7. Photo taken from the southwestern location, facing Southwest. Photo illustrates the topsoil stockpile with weed establishment. The temporary BMP (equipment tracking) is no longer in proper functioning condition. Stockpile needs to be stabilized as topsoil is starting to erode into the stormwater ditch.



Photo 8. Photo taken from the southern location on top of the topsoil stockpile, facing East. See comments under Photo 7.



Photo 9. Photo taken from the southern location, facing Southeast. Photo illustrates that the topsoil stockpile needs to be stabilized as topsoil is starting to erode into the stormwater ditch.

Inspection Photos
Location Name:CC31-02 /Pad
Location ID: 460265



Photo 10. Photo taken of the topsoil stockpile signage.



Photo 11. Photo taken from the northern location, facing West. Cut slopes are been temporarily stabilized with equipment tracking.