

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 1 – Location photo.



Photo 2 – Access to location unsecured upon COGCC arrival.

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 3 – Dirt being tracked off location onto neighborhood road.



Photo 4 – Dirt being tracked off location onto neighborhood road.

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 5 – Open excavation, Spill ID 481051



Photo 6 – Open excavation, Spill ID 481051

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 7 – Open excavation, Spill ID 481051



Photo 8 – Open excavation, Spill ID 482224

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 9 – Open excavation, Spill ID 482224



Photo 10 – Trash on location

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 11 – Soil stockpile with 'Contaminated' sign



Photo 12 – Soil stockpile area

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 13 – Soil stockpile



Photo 14 – Ripped lining at soil stockpile

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 15 – Ripped lining at soil stockpile



Photo 16 – Soil stockpile with ripped lining and inadequate stormwater BMPs

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 17 – Downed silt fence



Photo 18 – Downed silt fence

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 19 – Improperly installed silt fence



Photo 20 – Improperly installed silt fence

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 21 – Improperly installed silt fence



Photo 22 – Improperly installed silt fence

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



8/17/2022 Drone Imagery – 1.55 Total Acres disturbed