

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2022

Submitted Date:

08/25/2022

Document Number:

702400955

FIELD INSPECTION FORM

Loc ID 426111 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | Inspections@civiresources.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 426360 | WELL | PR | 08/01/2019 | OW | 123-34663 | MELBON RANCH 3A-17H | PR |

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|----------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

| Spills: | | | | |
|----------------|------|--------|--|--|
| Type | Area | Volume | | |
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| Fencing/: | | | |
|--------------------|-----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | chainlink | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | chainlink | | |
| Corrective Action: | | Date: | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | chainlink | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | fabricated steel pipe | | |
| Corrective Action: | | Date: | |

| Equipment: | | | corrective date |
|---------------------------|-----|-------|-----------------|
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |

| | | |
|--|-----|-------|
| Comment: generator and electric panel | | Date: |
| Corrective Action: | | Date: |
| Type: Prime Mover | # 1 | |
| Comment: electric motor | | Date: |
| Corrective Action: | | Date: |
| Type: | # | |
| Comment: See Inspection Doc # 702400953 for related shared facilities and equipment. | | Date: |
| Corrective Action: | | Date: |
| Type: Bradenhead | # 1 | |
| Comment: appears plumbed to surface | | Date: |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--|---|----------|------|---------|--------|
| | | | | | |
| Comment: See Inspection Doc # 702400953 for related shared facilities and equipment. | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | Date: |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | Date: |
| Comment: | | Date: |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | |
| | Date: |

Inspected Facilities

Facility ID: 426360 Type: WELL API Number: 123-34663 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/11/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary On Thursday 8-25-2022 at approximately 1115 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Civitas/Crestone Peak Resources Location name: Melbon Ranch 3A-17H-M265 API #05-123-34663 County: Weld Weather: Clear. Location: Dry. While there, I observed a Multi well Pad, PR at the time of inspection. During this inspection, I observed no compliance issues: See attached photos. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p> | revasr | 08/25/2022 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 702400956 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5840343 |