

Inspection Photos

API: 071-08576

Operator: RED RIVER RANCH HOLDINGS LLC

Inspection Date: 8/25/2022



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08576 | Date: 8/25/2022

Inspection Photos



Photo 1. There has been work done to repair erosion at the water bars.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08576 | Date: 8/25/2022

Inspection Photos



Photo 2. Additional stabilization should be performed at the red arrow where stormwater is diverted toward.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08576 | Date: 8/25/2022

Inspection Photos



Photo 3. Facing down north along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08576 | Date: 8/25/2022

Inspection Photos



Photo 4. Facing northeast toward the location. There is erosion in this area where stormwater is directed toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08576 | Date: 8/25/2022

Inspection Photos



Photo 5. Facing east toward the location. The location is stabilized with native perennial vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08576 | Date: 8/25/2022

Inspection Photos



Photo 6. Facing southwest at the location. The location is stabilized with native perennial vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08576 | Date: 8/25/2022