

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/10/2022

Submitted Date:

08/24/2022

Document Number:

697504120

**FIELD INSPECTION FORM**Loc ID 460265 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name     | Phone | Email                                                 | Comment         |
|------------------|-------|-------------------------------------------------------|-----------------|
|                  |       | al.stafford@state.co.us                               |                 |
| Edwardson, Dylan |       | dylan.edwardson@state.co.us                           |                 |
| ,                |       | rbucogccinspectionreports@c<br>hevron.onmicrosoft.com | All Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 460255      | WELL | AP     | 12/21/2018  |            | 123-49272 | Booth CC30-725         | CI          |
| 460256      | WELL | AP     | 12/21/2018  |            | 123-49273 | BOOTH FEDERAL DD06-730 | CI          |
| 460257      | WELL | AP     | 12/21/2018  |            | 123-49274 | BOOTH FEDERAL DD06-734 | CI          |
| 460258      | WELL | AP     | 12/21/2018  |            | 123-49275 | BOOTH FEDERAL DD06-745 | CI          |
| 460259      | WELL | AP     | 12/21/2018  |            | 123-49276 | Booth CC30-715         | CI          |
| 460260      | WELL | AP     | 12/21/2018  |            | 123-49277 | Booth CC30-734         | CI          |
| 460261      | WELL | AP     | 12/21/2018  |            | 123-49278 | BOOTH FEDERAL DD06-715 | CI          |
| 460262      | WELL | AP     | 12/21/2018  |            | 123-49279 | Booth CC30-745         | CI          |
| 460264      | WELL | AP     | 12/21/2018  |            | 123-49280 | BOOTH FEDERAL DD06-725 | CI          |

**General Comment:**

This is a joint inspection with the CDPHE Water Quality Control Division. CDPHE conducted a construction stormwater inspection for the Noble Energy DJ Basin Core Drilling and Production Program (COR403291) and COGCC Staff participated in the inspection.

COGCC will not issue any corrective actions that would also be a corrective action for CDPHE.

### Location Construction

Location ID: 460265 CDP: \_\_\_\_\_

Comment: Operator submitted a Form 42: Notice of construction on 4/5/2022- Document # 403005228.  
Per Rule 406.c. a copy of the approved Form 2A was posted at the east location entrance.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### Form 2A COAs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### Wildlife BMPs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

| Inspected Facilities       |                   |                              |                   |                         |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>460255</u> | Type: <u>WELL</u> | API Number: <u>123-49272</u> | Status: <u>AP</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>460256</u> | Type: <u>WELL</u> | API Number: <u>123-49273</u> | Status: <u>AP</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>460257</u> | Type: <u>WELL</u> | API Number: <u>123-49274</u> | Status: <u>AP</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>460258</u> | Type: <u>WELL</u> | API Number: <u>123-49275</u> | Status: <u>AP</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>460259</u> | Type: <u>WELL</u> | API Number: <u>123-49276</u> | Status: <u>AP</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>460260</u> | Type: <u>WELL</u> | API Number: <u>123-49277</u> | Status: <u>AP</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>460261</u> | Type: <u>WELL</u> | API Number: <u>123-49278</u> | Status: <u>AP</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>460262</u> | Type: <u>WELL</u> | API Number: <u>123-49279</u> | Status: <u>AP</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>460264</u> | Type: <u>WELL</u> | API Number: <u>123-49280</u> | Status: <u>AP</u> | Insp. Status: <u>CI</u> |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND \_\_\_\_\_ Pass \_\_\_\_\_

Comment \_\_\_\_\_

Appears topsoil was salvaged and stored along the southern and portions of the southwestern perimeter of the location in compliance with Rule 1002.b. Refer to the attached inspection photos.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_ Fail \_\_\_\_\_

Comment \_\_\_\_\_

The topsoil stockpile had been temporarily stabilized with equipment tracking for short-term stabilization; however, the temporarily stabilization is no longer in proper functioning condition. Evidence of erosion was observed on the stockpile which is starting to erode into portions of the ditch BMP. Also, the topsoil had established weed growth with no desirable vegetation.

Per Rule 1002.c., all stockpiles shall be protected from wind and water erosion during drilling and production operations and BMPs to prevent weed establishment shall be implemented.

Corrective Action \_\_\_\_\_

Comply with Rule 1002.c to stabilize the stockpile and implement BMPs to prevent weed establishment.

Date **08/10/2022**

The corrective date is the date the location was observed out of compliance, as it should be in compliance at all times.

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|                  |                 |                         |                       |               |                          |         |

Comment: [Stormwater management repairs are needed. CDPHE is requiring corrective actions; therefore, COGCC will not issue a corrective action.](#)

Corrective Action:  Date: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment                                                                                                                                                                                                                                                                                                                           | User      | Date       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|------------|
| <a href="#">COGCC Staff, Chris Binschus, also participated in the follow-up post-inspection meeting with CDPHE and the Operator on Friday, August 12th. COGCC shared its outcome of the stormwater management practices observed throughout the ten locations and gave further guidance on topsoil management best practices.</a> | binschusc | 08/24/2022 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL                                                                                                                                                                 |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 403146434    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5839430">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5839430</a> |
| 697504121    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5839429">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5839429</a> |