

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/30/2022

Submitted Date:

08/31/2022

Document Number:

702500371**FIELD INSPECTION FORM**Loc ID 385876 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417451	WELL	PR	10/16/2010	CBM	067-09816	HEIN 1-2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

At time of inspection construction crew on site performing pipe tie ins for gas collection network.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment: Pump jack enclosed by sound panels.

Corrective Action:

Date:

Equipment:

corrective date

Type: Prime Mover

1

Comment: Gas powered

Corrective Action:

Date:

Type: Flow Line

9

Comment: 3" line from wellhead to separator, line from separator to produced water, 1" line from separator to gas powered prime mover, additional 2" water line at separator, 5 2" water lines at produced water tank battery.

Corrective Action:

Date:

Type: Bird Protectors

9

Comment: Separator vent stack and produced water tanks are screened properly.

Corrective Action:

Date:

Type: Vertical Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: Bradenhead is accessible.

Corrective Action:

Date:

Type: Ancillary equipment

2

Comment: Telemetry, water meter house

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: Gas meter calibration is within the last year

Corrective Action:

Date:

Type: Other

#

Comment:	Gas generator lube oil earth berm height is diminished (IMG 03).			
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention per rule 1002.f.(2)B.		Date:	09/14/2022
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	8	500 BBLs	STEEL AST		37.043329,-107.565380	
Comment:	Above ground produces water tank battery. 8 tanks each with 500 bbl capacity.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Metal barrier with liner.				
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 417451	Type: WELL	API Number: 067-09816	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass					
				Material Handling And Spill Prevention	In Process	
Gravel	Pass					
		Compaction	Pass			
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
A follow up inspection will be conducted once construction is completed.	klinka	08/30/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500372	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844439