

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/31/2022

Submitted Date:

08/31/2022

Document Number:

702500377**FIELD INSPECTION FORM**Loc ID 334189 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260538	WELL	PR	02/10/2002	CBM	067-08488	LEMON K 2	PR
282626	WELL	PR	01/17/2006	CBM	067-09101	LEMON K 4	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank capacity is not labeled (IMG 03).		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 09/30/2022

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Wellheads and equipment at this location are enclosed by stock panel.		
Corrective Action:			Date:

Equipment:

			corrective date
Type: Other	# 2		
Comment:	Linear rod pump		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Telemetry, electric cabinet, 2 pump control panels		
Corrective Action:			Date:
Type: Flow Line	# 6		
Comment:	2 3" and 2 2" lines from wellheads to separators, 4" line from gas meter run to off location, line from separators to produced water		
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	Electric		
Corrective Action:			Date:
Type: Bird Protectors	# 1		

Comment:	Separator vent stack is screened properly			
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:	Gas meter calibrations are within the last year			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.194044,-107.764502	
Comment:	Partially buried produced water tank.					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl	
Other (Type)	cone top	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities

Facility ID: 260538 Type: WELL API Number: 067-08488 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 05/24/2021Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Last reported bradenhead test date: 5/24/202109/30/2022Corrective Action: Confirm bradenhead test has been submitted or perform annual bradenhead test per rule 419.cDate:

Facility ID: 282626 Type: WELL API Number: 067-09101 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 05/24/2021Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Last reported bradenhead test date: 5/24/202109/30/2022Corrective Action: Confirm bradenhead test has been submitted or perform annual bradenhead test per rule 419.cDate:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Compaction	Pass			
Gravel	Pass					
Rip Rap	Pass					
Compaction	Pass					

Comment: [Erosion channel beginning to form on southern edge of location \(IMG 04\).](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500378	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5845167