

STATE OF COLORADO  
OIL AND GAS CONSERVATION COMMISSION  
DEPARTMENT OF NATURAL RESOURCES

99999999

SUBMIT ORIGINAL AND 1 COPY

FOR OFFICE USE ONLY			
ET	FE	UC	SE

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> COALBED METHANE <input type="checkbox"/> INJECTION WELL <input type="checkbox"/> OTHER			5 FEDERAL, INDIAN OR STATE LEASE NO
2 NAME OF OPERATOR Rex Monahan			6 PERMIT NO.
3 ADDRESS OF OPERATOR Box 1231			7 API NO 05 075 6335
CITY Sterling	STATE Colorado	ZIP CODE 80751	8 WELL NAME Mt. Hope Green
4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. Set also space 17 below ) At surface			9 WELL NUMBER #34
At proposed prod. zone			10 FIELD OR WILDCAT Mt. Hope
12 COUNTY Logan			11 QTR. QTR. SEC., T.R. AND MERIDIAN SENE Sec. 25-9N-54W ✓

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

## 13A. NOTICE OF INTENTION TO:

- ☒ PLUG AND ABANDON  
☐ MULTIPLE COMPLETION  
☐ COMMINGLE ZONES  
☐ FRACTURE TREAT  
☐ REPAIR WELL  
☐ OTHER

## 13B. SUBSEQUENT REPORT OF:

- ☐ FINAL PLUG AND ABANDONMENT  
(SUBMIT 3RD PARTY CEMENT VERIFICATION  
AND JOB LOG)  
☐ ABANDONED LOCATION (WELL NEVER DRILLED -  
SITE MUST BE RESTORED WITHIN 6 MONTHS)  
☐ REPAIRED WELL  
☐ OTHER

\*Use Form 5 - Well Completion or Recompletion Report and Log  
for subsequent report of Multiple/Commingle Completions  
and Recompletions

## 13C. NOTIFICATION OF:

- ☐ SHUT-IN TEMPORARILY ABANDONED  
(DATE \_\_\_\_\_)  
(REQUIRED EVERY 6 MONTHS)  
☐ PRODUCTION RESUMED  
(DATE \_\_\_\_\_)  
☐ LOCATION CHANGE (SUBMIT NEW PLAT)  
☐ WELL NAME CHANGE  
☐ OTHER

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent)

15. DATE OF WORK September, 1994

- Run tubing to the bottom of the wellbore at approximately 5160' KB. Circulate approximately 120 bbls. of 9.0#/Gal. fresh water drilling mud into the wellbore.
- Through tubing circulate a 10-sack Portland cement plug to approximately 5160' KB (btm. of plug) Set a 10-sack Portland cement plug with its base at approximately 4895' KB (circulated through the tubing).
- Cut the 7"O.D., 20# & 23#/ft. casing at approximately 4300'KB (Estimated cement top - 4460' KB) Pull the casing.
- Set a 30-sack Portland cement plug half in and half out of the casing stub (circulated through tubing).
- Set a 40-sack Portland cement plug half in and half out of the base of the surface casing (circulated through tubing).
- Pump a 15-sack Portland cement plug through tubing into the top of the surface casing.

16. I hereby certify that the foregoing is true and correct



00255522

(OVER)

SIGNED

NAME (PRINT)

Rex Monahan

TITLE

Operator

DATE

9-12-94

TELEPHONE NO. 303-522-0774

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

SET 20 SX PLUG AT 5160' AND 4895'

NOTIFY ED BINKLEY (970-842-4465) PRIOR TO PLUGGING.

SR. PETROLEUM ENGINEER

O &amp; G Cons. Comm.

DATE

NOV 24 1995

7. Cut off the surface casing 4' below ground level. Weld a steel plate onto its top. Return the surface to its original contour.