

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/06/2022

Submitted Date:

09/06/2022

Document Number:

702500395

FIELD INSPECTION FORM

 Loc ID 312122 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 7650
 Name of Operator: BENSON-MONTIN-GREER DRILLING CORPORATION
 Address: 4900 COLLEGE BLVD
 City: FARMINGTON State: NM Zip: 87402
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Stradling, Zak	(505) 324-5074	zstradling@bmgdrilling.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214684	WELL	PR	10/01/2020	GW	067-06288	FLUME CANYON 4	WK
259743	WELL	PR	09/01/2020	GW	067-08421	SOUTHERN UTE 16-6	PR

General Comment:

Inspector Alex Klink on site at 11:20 AM to observe and witness plugging operations. See link at end of report for inspection photos.

At 11:20 AM the well was blown down and current operations were retrieving packer at 4488'.

The packer did not come free, wireline truck rigged up, cut the tubing at 4460'. Tubing and packer will still not come free.

Well was blown down into open top tanks with no emission capture, control, or combustion, as COA from Form 6 requires. There was 350 PSI on the tubing when blow down commenced, and blow down lasted ~1 hour. Portable toilet was strapped and secured from being knocked over. Directional rig signs were installed, and 4 fire extinguishers on site.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Horizontal Heated Separator	# 1				
Horizontal Heated Separator	# 1				
Flow Line	# 3	2" line from wellhead to separator, 2" line at separator, 2" riser with valve,			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV PLASTIC		37.108457,-107.933066
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	21bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 214684 Type: WELL API Number: 067-06288 Status: PR Insp. Status: WK

Cement

Cement Contractor

Contractor Name: A+ Well Service

Contractor Phone: (505) 325-2627

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Person in Charge: Santiago Soliz
At 11:20 AM the well was blown down and current operations were retrieving packer at 4488'.
The packer did not come free, wireline truck rigged up, cut the tubing at 4460'. Tubing and packer will still not come free.

Corrective Action: _____

Date: _____

Facility ID: 259743 Type: WELL API Number: 067-08421 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					
		Gravel	Pass			
		Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500396	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5849215