

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/30/2022

Submitted Date:

08/31/2022

Document Number:

702500365

**FIELD INSPECTION FORM**
 Loc ID 325498 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 25250

Name of Operator: DUGAN PRODUCTION CORP

Address: P O BOX 420

City: FARMINGTON State: NM Zip: 87499-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Armenta, Bill	505-325-1821	billarmenta@duganproduction.com	<a href="#">All SW Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	
Smaka, Kevin	505-325-1821	kevin.smaka@duganproduction.com	<a href="#">Sw Insp Reports</a>
Alexander, John		john.alexander@duganproduction.com	<a href="#">All SW Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214894	WELL	PR	02/28/2011	GW	067-06498	TIFFANY 1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Lube oil from compressor skid has impacted surface materials (IMG 06).		
Corrective Action:	Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.		Date: 09/14/2022
Type	UNUSED EQUIPMENT		
Comment:	Fuel container (IMG 05), muffler hose by southern separator (IMG 04), and muffler hose by north produced water tank (IMG 09) are unused equipment.		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.  Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k		Date: 09/14/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Northern separator and produced water tank are enclosed by metal safety fence, southern produced water tank enclosed by wire fencing.		
Corrective Action:			Date:

**Equipment:**

			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas meter run is off location. Gas meter calibration is within the last year.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Telemetry, cathodic protection, solar panel on north edge of location.		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	Compressor skid		
Corrective Action:			Date:
Type: Flow Line	# 5		
Comment:	2" line from wellhead to northern separator, line from northern separator to northern produced water tank, 2" line from northern separator to southern separator, 2" line from northern separator to northern produced water tank, 4" line from southern separator to gas meter run off location.  3/4" flow line near southern edge of location is not in use and is not locked out/tagged out.		

Corrective Action:	Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)		Date:	09/02/2022
Type: Bradenhead	# 1			
Comment:	Bradenhead is accessible.			
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 2			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:	Separator vent stacks are screened properly.			
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	OTHER		37.036016,-107.581546
Comment:	Above ground produced water tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	50 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Diminished berm height on eastern edge of secondary containment (IMG 10).			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	OTHER		37.035734,-107.581454
Comment:	Above ground produced water tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	45 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Compacted gravel earth berm		
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	214894	Type:	WELL	API Number:	067-06498	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Fail			
Gravel	Fail					
		Compaction	Fail			
Compaction	Fail					
				Material Handling And Spill Prevention	Pass	

Comment: [Access road and location have developed ruts up to 12" deep \(IMG 07 and IMG 08\). Similar conditions were observed in previous inspections Doc# 693900807 and Doc# 687905647.](#)

Corrective Action: [Maintain access road and location conditions per rule 1002.f\(2\)F. Emergency vehicles must be able to access location in inclement weather conditions.](#)

Date: 09/16/2022

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403152556	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844441">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844441</a>
702500366	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844438">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844438</a>