

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

08/30/2022

Submitted Date:

08/31/2022

Document Number:

702500371

**FIELD INSPECTION FORM**
 Loc ID 385876 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		FarmingtonRegulatoryTechs@hilcorp.com	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417451	WELL	PR	10/16/2010	CBM	067-09816	HEIN 1-2	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

At time of inspection construction crew on site performing pipe tie ins for gas collection network.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	Pump jack enclosed by sound panels.		
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	# 2		corrective date
Comment:	Telemetry, water meter house		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	Gas generator lube oil earth berm height is diminished (IMG 03).		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention per rule 1002.f.(2)B.	Date:	09/14/2022
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:	Separator vent stack and produced water tanks are screened properly.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas powered		

Corrective Action:		Date:	
Type: Flow Line	# 9		
Comment:	3" line from wellhead to separator, line from separator to produced water, 1" line from separator to gas powered prime mover, additional 2" water line at separator, 5 2" water lines at produced water tank battery.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	8	500 BBLS	STEEL AST		37.043329,-107.565380	
Comment:	Above ground produces water tank battery. 8 tanks each with 500 bbl capacity.					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Metal barrier with liner.				
Corrective Action:				Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	417451	Type:	WELL	API Number:	067-09816	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	In Process	
Gravel	Pass					
		Gravel	Pass			
Compaction	Pass					
		Compaction	Pass			
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
A follow up inspection will be conducted once construction is completed.	klinka	08/30/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403152558	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844442">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844442</a>
702500372	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844439">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5844439</a>