

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 1 – Location photo.



Photo 2 – Access to location secured upon COGCC arrival.

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 3 – Dirt being tracked off location observed in previous inspection has been cleaned. No maintenance appears to have been performed on vehicle tracking pad.



Photo 4 – Dirt being tracked off location observed in previous inspection has been cleaned. No maintenance appears to have been performed on vehicle tracking pad.

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 5 – Open excavation, Spill ID 481051



Photo 6 – Open excavation, Spill ID 481051

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 7 – Previously stored contaminated soil has been removed from location. One pile of soil for backfill has been stored on site.



Photo 8 – Previously observed trash has been removed from location.

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 9 – Silt fence is inadequately installed



Photo 10 – Silt fence is inadequately installed

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 11 – Silt fence is inadequately installed



Photo 12 – Silt fence is inadequately installed

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 13 – Silt fence is inadequately installed



Photo 14 – Silt fence beginning to fall

Inspection Photos
Morgan A1
Spill ID 481051 (CL) & 482224 (AC)



Photo 15 – Photo provided by KPK to COGCC documenting silt fence was repaired after COGCC left location.