

Inspection Photos
Location Name: Josephine B Miles #5
Location ID:318991



Photo 1 Sept 1 inspection to confirm well is shut in



Photo 2 loc pic

Inspection Photos
Location Name: Josephine B Miles #5
Location ID:318991



Photo 3 mechanical issue 2" flow line leaking around hammer union



Photo 4 Weeds around electric equipment.

Inspection Photos
Location Name: Josephine B Miles #5
Location ID:318991



Photo 5 well sign faded not legible