

Inspection Photos
Location Name: Champlin 86 Amoco B #2
Location ID: 318253



Photo 1 Sept 1 inspection to confirm well is shut in



Photo 2 loc pic, weeds on site

Inspection Photos
Location Name: Champlin 86 Amoco B #2
Location ID: 318253



Photo 3 TNK BTRY



Photo 4 ECD Weeds on location

Inspection Photos
Location Name: Champlin 86 Amoco B #2
Location ID: 318253



Photo 5 unused equipment broken pipe. Weeds around separator.



Photo 6 meter run

Inspection Photos
Location Name: Champlin 86 Amoco B #2
Location ID: 318253



Photo 7 Well head sign faded not legible



Photo 8 loc pic weeds on location.