

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2022

Submitted Date:

09/07/2022

Document Number:

697601874

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1700 LINCOLN ST STE 4550
 City: DENVER State: CO Zip: 80203

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Cuthbertson, Scott		scott.cuthbertson@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
-, Marcom		primarycontractor@marcomllc.net	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

General Comment:

Environmental inspection of Spill ID 482755 reported by Operator 8/13/2022 for the spill of oil, produced water, and condensate from the Rodgers #1 Flowline.
 Environmental Inspections conducted 8/15/2022, 8/17/2022, 8/22/2022, 8/25/2022, 8/29/2022, 8/30/2022, and 9/1/2022.
 At the time of inspection, crews were onsite and continuing remediation work on the spill excavations using a backhoe. Staining and high hydrocarbon odor were prevalent within the spill excavations.
 A total of two excavations and one spill excavation was present at location; two excavations open for flowline repair and one consolidated spill excavation.

Location

Overall Good:

Emergency Contact Number:

Comment: Warning signage with an emergency phone number has been installed on location.

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:				
Type	OTHER			
Comment:	Operator has installed both cattle panel fencing surrounding the orange construction fencing around all excavations.			
Corrective Action:			Date:	

Venting:				
Yes/No				
Comment:				
Corrective Action:			Date:	

Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Environmental

Spill/Remediation:

Comment: Remediation continued at the spill location. Crews were onsite using a backhoe to dig at the excavation. The two hydrovaced pothole excavations have been consolidated into one large excavation. Contaminated soil was emptied into a waste truck and hauled offsite. Obvious impacts remain visible in-situ. Hydrocarbon odors present outside of fencing.

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601875	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5850352