

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/08/2022

Submitted Date:

09/08/2022

Document Number:

702500416

**FIELD INSPECTION FORM**Loc ID 326167 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215984	WELL	PR	12/08/1990	CBM	067-07590	THOMAS JACQUEZ E 1	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Stairs at produced water are not in use (IMG 05). Unused sack of material is deteriorated and unused (IMG 06), traffic marker and base are not in use (IMG 07 and IMG 08), barrel with broken headphones and wires (IMG 09) are unused.		
Corrective Action:	All unused equipment must be returned to use or stored off location per rule 606.	Date:	09/17/2022
Type	WEEDS		
Comment:	Weeds near produced water tank and compressor. (IMG 03 and IMG 04)		
Corrective Action:	Control weeds per rule 606.  Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k	Date:	09/17/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Location enclosed by chain link fence with barbed wire, compressor enclosed by sound panel, produced water tank enclosed by sound panel.		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Flow Line	# 6		
Comment:	6" line from wellhead to separator, 6" line from separator to compressor, 6" line from compressor to gas meter run, 6" line from gas meter run to off location, line from separator to produced water. 1" line at produced water tank battery		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	All vents are screened.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		

Comment:		Date:	
Corrective Action:		Date:	
Type: Other	#		
Comment:	Chemical containers with spill prevention. Lube oil within secondary containment is nearly full (IMG 10).		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is within the last year.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Telemetry, valve pit cluster, produced water transfer pump, electric house		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	OTHER		37.103135,-107.897960
Comment:	2 above ground produced water tanks each with 400 bbl capacity				
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	400 bbl each
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV STEEL		37.103399,-107.898655
Comment:	Partially buried produced water				
Corrective Action:			Date:		

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	21 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 215984	Type: WELL	API Number: 067-07590	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Compaction	Pass					
Gravel	Pass					
Berms	Pass					
				Material Handling And Spill Prevention	Pass	
		Gravel	Pass			
Ditches	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500417	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5851715">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5851715</a>