

Inspection Photos

API: 071-08419

Operator: OGRIS OPERATING LLC

Inspection Date: 9/8/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08419 | Date: 9/8/2022

Inspection Photos



Photo 1. Facing north along the road. The road side is eroding in this area due to concentrated stormwater flow. BMP's need to be installed in this area (e.g. check dams, rip/rap).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08419 | Date: 9/8/2022

Inspection Photos



Photo 2. Just past the compressor facility, stormwater is not properly diverted off the road in this area and is flowing past the diversion shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08419 | Date: 9/8/2022

Inspection Photos



Photo 3. There is erosion occurring at the access road. Which is not being diverted toward the rock rip/rap outlet.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08419 | Date: 9/8/2022

Inspection Photos



Photo 4. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08419 | Date: 9/8/2022