

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/05/2022

Submitted Date:

09/05/2022

Document Number:

702500389

FIELD INSPECTION FORMLoc ID 334051 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10755

Name of Operator: MORNINGSTAR OPERATING LLC

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Kittinger, Eric		ekittinger@mspartners.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277576	WELL	PR	05/11/2005	CBM	007-06212	SWANEMYR 32-6 1-2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

This inspection does not include the Swanemyr 32-6 1-1. Please see Doc#702500390 for the #1-1 inspection

Location

Overall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical container sign is deteriorating (IMG 08).		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds established at wellhead and separators (IMG 09 and IMG 10).		
Corrective Action:	Control weeds per rule 606. Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k		Date: 09/14/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	#1-3 wellhead enclosed by stock panel, #1-2 wellhead enclosed by chain link fence with barbed wire. Separators and produced water tank are enclosed by wire fencing.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Pump jack is not in use at time of this inspection.		
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:	Gas meter calibrations are within the last year.		
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:	Bradenheads are accessible.		
Corrective Action:			Date:
Type: Flow Line	# 13		

Comment:	2 2" and 1" line from wellhead to separators, 2 2" lines from wellhead to separators, 3 2" lines from separators to produced water, 2" produced water line at separator from off location, 3 4" lines from gas meter run to off location, 1" line at produced water tanks.				
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:	Telemetry, produced water tank transfer pump electric panels				
Corrective Action:				Date:	
Type: Other	# 1				
Comment:	Produced water transfer pump in house adjacent to tanks.				
Corrective Action:				Date:	
Type: Bird Protectors	# 5				
Comment:	Separator and produced water tank vent stacks are screened properly.				
Corrective Action:				Date:	
Type: Plunger Lift	# 2				
Comment:					
Corrective Action:				Date:	
Type: Vertical Heated Separator	# 3				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	OTHER		37.042774,-107.446110
Comment:	2 above ground produced water tanks, each with 400 bbl capacity.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	400 bbl	
Other (Type)	cone top	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Weeds established on earth berms impacting berm permeability (IMG 11 and IMG 12). This is a similar comment from inspection Doc#685304987			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o. Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k			Date: 10/05/2022

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>277576</u>	Type: <u>WELL</u>	API Number: <u>007-06212</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment:				
Corrective Action:				Date: <div></div>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: [Water is flowing onto, across, and off locatoin \(IMG 05, 06, and 07\). Facilities must be operated in a manner that minimizes erosion, transport of sediment offsite, and site degradation.](#)

Corrective Action: [Install or repair/modify required BMPs per Rule 1002.f.\(2\)C](#)

Date: 10/05/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403155812	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5848055
702500391	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5848050