

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2022

Submitted Date:

09/12/2022

Document Number:

702500427

FIELD INSPECTION FORM

Loc ID 326615 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 18 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------------|--------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| , General | | sjninspections@ikavenergy.com | All SW field inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 259209 | WELL | PR | 06/13/2001 | CBM | 067-08403 | ARTHUR MASON A 2 | PR |
| 412490 | WELL | PR | 10/15/2021 | GW | 067-09763 | ARTHUR MASON A 4 | PR |

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Produced water tan sign not secured properly (IMG 05). | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 11/12/2022 |
| Type | WELLHEAD | | |
| Comment: | Well sign is deteriorated (IMG 01). | | |
| Corrective Action: | Install sign to comply with Rule 605.a. | Date: | 10/12/2022 |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|--|----------------------------|
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | STORAGE OF SUPL | | |
| Comment: | Landowner appears to be storing agricultural equipment on edge of location (IMG 04). | | |
| Corrective Action: | | Date: | |
| Type | WEEDS | | |
| Comment: | Weeds near produced water tank and separator (IMG 06). | | |
| Corrective Action: | Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k | Date: | 09/21/2022 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Pipe fittings are not in use (IMG 07 and IMG 08). | | |
| Corrective Action: | All unused equipment must be returned to use or stored off location per rule 606. | Date: | 09/28/2022 |
| Type | OTHER | | |
| Comment: | Impacted material at A 4 wellhead (IMG 03). | | |
| Corrective Action: | Remove impacted material and dispose of in approved manner per rule 906 and 1002.f. | Date: | 09/28/2022 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--|-------|--|
| Type | OTHER | | |
| Comment: | Equipment at this facility is enclosed by stock panel. | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------|----------|-------|-----------------|
| Type: Prime Mover | # 2 | | corrective date |
| Comment: | Electric | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|---|--|-------|
| Type: Other | # 1 | | |
| Comment: | Linear rod pump | | |
| Corrective Action: | | | Date: |
| Type: Flow Line | # 6 | | |
| Comment: | 2 3" and 2 2" lines from wellheads to separators, line from separators to produced water, 4" line from gas meter run to off location. | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenheads are accessible. | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 5 | | |
| Comment: | Telemetry, electric cabinet, valve cluster pit, 2 pump control panels, | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 1 | | |
| Comment: | tank vent stack is screened properly. | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 2 | | |
| Comment: | Gas meter calibrations are up to date. | | |
| Corrective Action: | | | Date: |
| Type: Vertical Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------------------------------------|-----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | <100 BBLS | PBV STEEL | | 37.176508,-107.855286 |
| Comment: | Partially buried produced water tank. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 95 bbl |
| Other (Type) | cone top |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---------------------|---------------------|---------------------|-------------|
| Other | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Double walled tank. | | | |
| Corrective Action: | | | | Date: |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 259209 Type: WELL API Number: 067-08403 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 412490 Type: WELL API Number: 067-09763 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Compaction | Pass | | | |
| Gravel | Pass | | | | | |
| | | Gravel | Pass | | | |
| Compaction | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 702500428 | Photo doc | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5857392 |