

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/01/2022

Submitted Date:

09/06/2022

Document Number:

700600416

**FIELD INSPECTION FORM**

Loc ID 324789 Inspector Name: Kosola, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 95620  
Name of Operator: WESTERN OPERATING COMPANY  
Address: 1165 DELAWARE STREET #200  
City: DENVER State: CO Zip: 80204

**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Dale	719-688-1638	dale@westernoperating.com	
James, Steven D.	303-893-2438	steve@westernoperating.com	President
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150024	UIC DISPOSAL	AC	09/08/1969		-	SALT WATER DISPOSAL 1	EI

**General Comment:**

Exposed flowline near tank battery. Operator informed of exposed line via phone call on 9-6-2022. Line is believed to be old unused gas line. Operator stated they will investigate and plug line.

Stained soil around wellhead.

Unused equipment on location

See corrective actions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment stored near wellhead.		
Corrective Action:	Comply with Rule 606	Date:	10/06/2022
Type	OTHER		
Comment:	Stained soil near wellhead.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.	Date:	10/06/2022

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Flow Line	#		corrective date
Comment:	Landowner reported exposed flow line. This inspection found flowline exposed by recent stormwater.		
Corrective Action:	Install flowlines and crude oil transfer lines to comply with rule 1102.d	Date:	10/07/2022
	Investigate flowline and plug or remove per 1100 series rules.		

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 150024 Type: UIC API Number: - Status: AC Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403156712	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5848728">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5848728</a>
700600417	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5848725">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5848725</a>