

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/06/2022

Submitted Date:

09/06/2022

Document Number:

702500397

FIELD INSPECTION FORM

Loc ID 312122 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Huntington, Heather		hhuntington@enduringresources.com	All SW field inspections
Walker, Kyle		kwalter@enduringresources.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214684	WELL	PR	10/01/2020	GW	067-06288	FLUME CANYON 4	WK
259743	WELL	PR	09/01/2020	GW	067-08421	SOUTHERN UTE 16-6	PR
475469	Domestic Tap	AC	04/17/2020		-	Domestic Tap 16NENE	AC

General Comment:

[Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.](#)

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank capacity is not labeled (IMG 03).		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	10/06/2022

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Compressor skid is enclosed by sound panel.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Produced water tank is enclosed by stock panel		
Corrective Action:		Date:	

Equipment:

Type	Quantity	Comment	Corrective Action	Date	corrective date
Ancillary equipment	# 1	Telemetry			
Other	# 1	Linear rod pump			
Flow Line	# 4	6" and 2" lines from wellhead to separator, 2" line from separator to produced water, 4" line from gas meter run to off location.			
Compressor	# 1				
Prime Mover	# 1	Electric			
Bird Protectors	# 1				

Comment:	Separator vent stack is screened properly.		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	Bradenhead is accessible.		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:	Gas meter calibration is within the last year.		Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:			Date:	
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.108186,-107.933807
Comment:	Partially buried tank with steel mesh top.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No		Date:
Comment:		
Corrective Action:		
		Date:

Flaring:

Type		Date:
Comment:		
Corrective Action:		
		Date:

Inspected Facilities

Facility ID: 214684 Type: WELL API Number: 067-06288 Status: PR Insp. Status: WK

Facility ID: 259743 Type: WELL API Number: 067-08421 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Facility ID: 475469 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Compaction	Pass			
Compaction	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403157301	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5849219
702500398	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5849216