



Diagram of the Getty Pan Am #19A Location

The original tank sat in the northeast corner of the pad. UGC is re-configuring the well pad because impacts were found in the soil during a flowline repair performed in spring 2022. The tank and flowline needed to be moved to the northwest corner of the pad because UGC will be sampling the soil where the original flowline was laid on a quarterly basis. The new pad layout is depicted by the white and orange polygons, and the red line.