

# Inspection Photos

Loc: 312051

Operator: SIMCOE/ LOGOS

Inspection Date: 8/30/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

## Inspection Photos



**Photo 1.** Facing southeast toward the location and production equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

## Inspection Photos



**Photo 2.** Facing southeast toward Bondad 33-9 equipment. The open top tank has been removed from this site. The remaining equipment needs to have improved secondary containment installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

## Inspection Photos



**Photo 3.** East side of the location facing northwest. The east/ northeastern portion of the location has not been revegetated with perennial vegetation. There has been no recent seeding and stabilization.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

## Inspection Photos



**Photo 4.** Facing southwest toward the Barnes A-2 well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

## Inspection Photos



**Photo 5.** Facing west toward the Barnes A-2 production equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

## Inspection Photos



**Photo 6.** Facing toward the below ground tank at the west side of the location. Barnes A-2 production equipment.



**Photo 7.** The tank has a steel pervious grate shown at red arrow. This needs to be covered to prevent overflow spillage.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

## Inspection Photos



**Photo 8.** Facing southwest at the west side of the location. This area of previous erosion was repaired and angular rock rip/rap has been installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

## Inspection Photos



**Photo 9.** Facing southwest at the west side of the location. Further along the bank the rock rip/rap changes to round rock which does not hold in place very well for proper stabilization. There are numerous noxious weeds in this area that need to be controlled. (Musk thistle, Hounds tongue, Canada thistle).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

## Inspection Photos



**Photo 10.** Facing northeast toward the swaled area along the stream bank. There has been rock rip/rap, wattles, and erosion blanket installed in this area where erosion had occurred.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

## Inspection Photos



**Photo 11.** Facing east toward the swaled area at the north side of the location. There has been rock rip/rap, wattles, and erosion blanket installed in this area where erosion had occurred.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

## Inspection Photos



**Photo 12.** Facing southwest at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Loc:312051 | Date: 8/30/2022

Inspection Photos



**Photo 13.** Facing southeast at the location.

