

Inspection Photos

API: 009-06236

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 9/13/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06236 | Date: 9/13/2022

Inspection Photos



Photo 1. Facing northeast toward wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06236 | Date: 9/13/2022

Inspection Photos



Photo 2. A new sign has been posted on the meter shed however, the sign does not meet the requirements of Rule 605.d.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06236 | Date: 9/13/2022

Inspection Photos



Photo 3. Facing toward the wellsite. The broken tank has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06236 | Date: 9/13/2022

Inspection Photos



Photo 4. This is the area the broken tank was at. There is an uncapped pipe riser at the red arrow that likely fed into the tank which need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06236 | Date: 9/13/2022

Inspection Photos



Photo 5. Facing toward the punmpjack. The debris around the pumpjack has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06236 | Date: 9/13/2022