

Inspection Photos

ID:438617

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 9/13/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 1. Facing northeast toward the gas treatment facility.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 2. There is an unused compressor stored on location that need to be removed. The compressor engine has various unconnected parts and does not appear to be functional. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 3. The facility sign is obscured behind the compressor. The sign does not meet the requirements and is not legible. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 4. Facing toward the open top tank. It appears the tank has previously leaked due to white stained soil. There is no secondary containment around the tank. There is no signage on the tank. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 5. The netting over the tank has been reinstalled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 6. There is equipment not maintained on location. Door has fallen off this shed. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 7. There is oil/chemical containers and trash not properly or disposed of. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 8. There is an open top tank at the east side of the location. It appears the tank has previously leaked due to white stained soil. There is no secondary containment around the tank. The signage has faded. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 9. There is oily stained soil at red arrow which appears to be fluids which were drained from the tank. Stained soil need to be cleaned up and properly disposed.



Inspection Photos



Photo 10. The liquid in the tank has been lowered.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 11. There are signs of a previous leak at the tanks due to white stained soils at the base of the tanks.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 12. Facing west toward the location. There is a plastic liner debris at east side of the location that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 13. There is unused supplies and a black barrels with no labeling. There are weeds and vegetation around the equipment which is a fire hazard. Previous corrective action is not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 14. Facing east toward the facility. There are weeds and vegetation around the equipment which is a fire hazard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 15. Facing north toward the facility. The surrounding disturbance area has areas that are bare of vegetation that need to be reclaimed per Rule 1003.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022

Inspection Photos



Photo 16. Facing east at the south side of the location. The surrounding disturbance area has areas that are bare of vegetation that need to be reclaimed per Rule 1003.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID:438617 | Date: 9/13/2022