

Inspection Photos

ID# 441082

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 9/13/2022



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 9/13/2022

Inspection Photos



Photo 1. Facing northeast toward the location. The disturbed location has not been reclaimed. Previous corrective actions were not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 9/13/2022

Inspection Photos



Photo 2. Facing northeast at the location. Soils are compacted and the location has not been reclaimed. Previous corrective actions were not performed. Soils must be decompacted by cross ripping to a depth of 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 9/13/2022

Inspection Photos



Photo 3. There are gravel and soil piles that remain at the north side of the location. The piles need to be removed. There are undesirable weeds on the piles.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 9/13/2022

Inspection Photos



Photo 4. Facing southwest at the north side of the location. There is undesirable throughout the location which must be controlled. There is metal debris shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 9/13/2022

Inspection Photos



Photo 5. Facing east at the location. There are piles of manure and material left on the location. There are undesirable weeds throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 9/13/2022

Inspection Photos



Photo 6. Facing west at the location. Soils are compacted and the location has not been reclaimed. Previous corrective actions were not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 9/13/2022

Inspection Photos



Photo 7. There is a cleanout junction 1850 ft. north of the pipeline which is associated with the former gas compressor station and must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 9/13/2022

Inspection Photos



Photo 8. Facing east toward the surrounding reference vegetation which consists of desirable vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 9/13/2022