

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4SWSW

Location ID: 324072



Photo #7674 From entrance to location.



Photo #7675 From entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4SWSW

Location ID: 324072



Photo #7677 Vent pipe on tank open ended.



Photo #7678 Loadline open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4SWSW

Location ID: 324072



Photo #7684 Unmarked deadman.



Photo #7680 Rill erosion occurring on cut slope.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4SWSW

Location ID: 324072



Photo #7681 Sediment encroaching on equipment.



Photo #7682 Run on to location is not being controlled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /4SWSW

Location ID: 324072



Photo #7683 Rill erosion occurring on access road.