

Inspection Photos

API: 009-06596

Operator: WEST TEXAS OPERATING CO

Inspection Date: 9/13/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06596 | Date: 9/13/2022

Inspection Photos



Photo 1. Facing southeast toward the wellsite. There are weeds around the pumpjack that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06596 | Date: 9/13/2022

Inspection Photos



Photo 2. Facing toward the open top tank. There is inadequate secondary containment around the tanks.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06596 | Date: 9/13/2022

Inspection Photos



Photo 3. The netting on the tank is in disrepair. Netting needs to be installed to prevent wildlife entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06596 | Date: 9/13/2022

Inspection Photos



Photo 4. There are signs of a leak that had occurred, perhaps from the piping. Stained soil needs to be cleaned up and the tank and piping need to be inspection for integrity.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06596 | Date: 9/13/2022

Inspection Photos



Photo 5. Well sign is posted by the pumpjack. The taped sign is peeled and faded and there is no emergency contact number.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06596 | Date: 9/13/2022

Inspection Photos



Photo 6. There is no labeling on the fiberglass tank and no secondary containment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06596 | Date: 9/13/2022

Inspection Photos



Photo 7. The pipe fence around the equipment is in need of maintenance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06596 | Date: 9/13/2022