

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2022

Submitted Date:

09/15/2022

Document Number:

690203404

FIELD INSPECTION FORM

Loc ID 321162 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10560
 Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME
 Address: PO BOX 2326
 City: VICTORIA State: TX Zip: 77902

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
6 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
HAHN MIKE		mhahn@xeogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256081	WELL	PR	03/01/2022	GW	009-06596	KEYSTONE 1-13	RI

General Comment:

[This is a location inspection.](#)
[See attached photos and additional details within this report.](#)

Location					
Lease Road:					
Type					
comment:					
Corrective ActionL					Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:					
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	There is no emergency company contact number on the well sign				Date:
Corrective Action:	Install sign to comply with Rule 605.d.				10/15/2022
Good Housekeeping:					
Type	WEEDS				
Comment:	There are weeds around the pumpjack which is a fire hazard.				
Corrective Action:	Comply with Rule 606. Remove weeds and debris from equipment area.				Date: 09/30/2022
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
Produced Water	Tank	<= 1 bbl			
Comment:	There are signs of a leak that had occurred, perhaps from the piping or tank. Stained soil needs to be cleaned up and the tank or piping need to be repaired/replaced to prevent leaks.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.				Date: 09/30/2022
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	TANK BATTERY				
Comment:	The pipe fencing around the equipment is in need of maintenance.				
Corrective Action:	Comply with fencing requirements.				Date: 09/30/2022
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
	2	200 BBLS	FIBERGLASS AST		
Comment:	The wildlife netting at the open top tank is in disrepair. Netting needs to be installed to prevent wildlife entry.				
Corrective Action:	Install or repair wildlife protection equipment.				Date: 09/30/2022
Paint					
Condition					

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
	Inadequate			Inadequate
Comment: There is inadequate secondary containment at the two tanks.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).				Date: <u>10/15/2022</u>

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690203405	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5861216