

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/14/2022

Submitted Date:

09/15/2022

Document Number:

688313124

FIELD INSPECTION FORM

Loc ID 309662 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10722
Name of Operator: KTM OPERATING LLC
Address: 2851 JOHNSTON ST PMB 550
City: LAFAYETTE State: LA Zip: 70503

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Lee, Kris		krislee@skybeam.com	
Hecht, Jaime	832-531-1711	jaime.hecht@dynacloud.io	
Vincent, Kenny	(337) 654-9404	kvincent@reagan.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300642	WELL	SI	03/01/2019	OW	073-06370	CRAIG 4-33	TA

General Comment:

MIT Inspection, passed
Reinspection, passed-sign, location mowed, MIT, road, and bradenhead.

Per COGCC Engineering, Operator took another bradenhead gas sample on 9/9/2022 and put 5 bbls water down the bradenhead making the pressure reverse pressure to -15 psi. Sample data will be submitted to COGCC database per Form 43 and to inspector. There is also 9/15/2020 bradenhead gas data that was submitted to COGCC Engineering.

Per inspection #688309667 INSP (CA 1) Submit Form 4 requesting TA status. ...2/6/2021. This was not done. COGCC wellbore diagram needs to be updated.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	see attached photo		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	WEEDS		
Comment:	are mowed		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 300642 Type: WELL API Number: 073-06370 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Update wellbore diagram to include curren CIBP depth.
Submit Form 4 TA status. Submit Form 21 electronically to COGCC database upon receipt of this inspection.
Casing prior to test 0 psi, Tubing is hanging in hole.
Bradenhead 15 psi.
0 min 340 psi
5 min 335 psi
10 min 335 psi
15 min 335 psi
lost 5 ppsi
Csing 0 psi after test
Form 21 is attached to inspection.

Corrective Action: Per inspection #688307644, "Submit Form 4 TA status....."

Date: 05/01/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688313126	KTM Craig 4-33 Form 21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5861322