

# Inspection Photos

API: 009-06624

Operator: ENERGY ALLIANCE COMPANY INC

Inspection Date: 9/13/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06624 | Date: 9/13/2022

## Inspection Photos



**Photo 1.** Facing north toward the location. There are areas that have not established desirable perennial vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06624 | Date: 9/13/2022

## Inspection Photos



**Photo 2.** This area of the location has no vegetation growth which indicates soil issues.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06624 | Date: 9/13/2022

## Inspection Photos



**Photo 3.** Facing back to the south at the location. This area of the location has no vegetation growth which indicates soil issues.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06624 | Date: 9/13/2022

## Inspection Photos



**Photo 4.** View of groundcover shows only undesirable weeds and bare soil.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06624 | Date: 9/13/2022

## Inspection Photos



**Photo 5.** Northeast of the location is a long area with inadequate vegetation growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06624 | Date: 9/13/2022

## Inspection Photos



**Photo 6.** Facing north toward the surrounding undisturbed reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06624 | Date: 9/13/2022