

**SWN PRODUCTION COMPANY LLC**  
**Dawson Creek 1-25**  
**Location # 424711**



**No sign at tank battery meeting Rule 605.e.. Signs have Beeman Oil & Gas on signs.**

**It was observed in this inspection that wildlife protection devices to prevent wildlife, including but not limited to birds and bats from entering the secondary containment. stock tank adjacent to the wellhead are missing or insufficient.**

**SWN PRODUCTION COMPANY LLC  
Dawson Creek 1-25  
Location # 424711**



**Methanol tank label is faded and missing information required for tanks over 10 bbls. Unused equipment including 2 tank stands, and 1 secondary containment tank were observed stored at the well area.**



**Methanol tank label is faded and missing information required for tanks over 10 bbls.**

**SWN PRODUCTION COMPANY LLC**  
**Dawson Creek 1-25**  
**Location # 424711**



**Methanol tank label is faded and missing information required for tanks over 10 bbls. Unused equipment including 2 tank stands, and 1 secondary containment tank were observed stored at the well area.**



**Methanol tank label is faded and missing information required for tanks over 10 bbls. Unused equipment including 2 tank stands, and 1 secondary containment tank were observed stored at the well area.**

**SWN PRODUCTION COMPANY LLC**  
**Dawson Creek 1-25**  
**Location # 424711**



**Propane tank not identified as a hazard and appropriate warning signs posted. Propane tank missing information required for tanks over 10 bbls.**



**Propane tank not identified as a hazard and appropriate warning signs posted. Propane tank missing information required for tanks over 10 bbls.**

**SWN PRODUCTION COMPANY LLC**  
**Dawson Creek 1-25**  
**Location # 424711**



**Propane tank not identified as a hazard and appropriate warning signs posted. Propane tank missing information required for tanks over 10 bbls.**



**Weeds around combustor.**

**SWN PRODUCTION COMPANY LLC**  
**Dawson Creek 1-25**  
**Location # 424711**



**Impacted soils observed around the production equipment at the north of the Location. The containment device at the spill at the north of the Location was observed to be insufficient.**

**Impacted soils observed around the production equipment at the north of the Location. The containment device at the spill at the north of the Location was observed to be insufficient.**

**SWN PRODUCTION COMPANY LLC**  
**Dawson Creek 1-25**  
**Location # 424711**



**Impacted soils observed around the wellhead**

**Impacted soils observed around the wellhead**

**SWN PRODUCTION COMPANY LLC**  
**Dawson Creek 1-25**  
**Location # 424711**



**Weeds on access road.**



**Weeds on access road.**

**SWN PRODUCTION COMPANY LLC**  
**Dawson Creek 1-25**  
**Location # 424711**



**Weeds on access road.**



**Weeds on access road.**

**SWN PRODUCTION COMPANY LLC**  
**Dawson Creek 1-25**  
**Location # 424711**



**Weeds on location.**



**Weeds on location.**

**SWN PRODUCTION COMPANY LLC**  
**Dawson Creek 1-25**  
**Location # 424711**



**Weeds on location.**



**Weeds on location.**