

Inspection Photos

API: 009-06082

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 9/13/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-06082 | Date: 9/13/2022

Inspection Photos



Photo 1. Facing east toward the location. The door to the meter shed is in disrepair and laying on the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06082 | Date: 9/13/2022

Inspection Photos



Photo 2. Missing tank NFPA labeling and missing INFO per 605.h.. Secondary containment is inadequate to contain 150% of the volume of the tank. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06082 | Date: 9/13/2022

Inspection Photos



Photo 3. View of fluids inside the tank. Tank is labeled Produced Water. It appears to be solidified salty produced water. The netting on the tank is in disrepair. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06082 | Date: 9/13/2022

Inspection Photos



Photo 4. There appears to have been a leak at the tank due to stained soil in this area. If tank contains produced salty water, this can impact the soil and crop growth. Previous corrective action not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06082 | Date: 9/13/2022

Inspection Photos



Photo 5. Well sign is posted at wellhead. Emergency contact number is not valid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06082 | Date: 9/13/2022