

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2022

Submitted Date:

09/15/2022

Document Number:

690203410

**FIELD INSPECTION FORM**Loc ID 320982 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

6 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Levengood, John		jlevengood07@gmail.com	
COGCC Enforcement		dnr_cogccenforcement@state.co.us	
GEORGE KELLY		envexbaca@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205671	WELL	PR	12/17/2012	GW	009-06082	BISHOP, E 1-29	RI

**General Comment:**

This is a follow up of the previous inspections; #690201497, #690201703, #690202890.  
 The previous inspection corrective actions have not been completed.  
 Non-compliance with the Rules will be referred to enforcement.  
 See attached photos and additional details within this report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	The tank label does not comply with 605. Missing tank NFPA labeling and missing INFO. Previous corrective action not completed.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/23/2021

**Emergency Contact Number:**

Comment:	Sign posted at well site however emergency contact number is not correct. Previous corrective action not completed.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	07/23/2021

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	If the tank is not in use it needs to be removed. The tank contains a solidified substance that is half full.		
Corrective Action:	Comply with Rule 606	Date:	12/10/2021
Type	DEBRIS		
Comment:	The door on the meter shed is laying on the ground and the meter shed is in disrepair.		
Corrective Action:	Comply with Rule 606	Date:	05/13/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		37.318570,-102.284340	
Comment:	There is an open top fiberglass tank at the location. The netting on the tank is in disrepair. The tank contains a solidified substance that is half full. Previous corrective action not completed					
Corrective Action:	Install or repair wildlife protection equipment.				Date:	05/13/2021

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
	Inadequate			Inadequate
Comment:	There is inadequate secondary containment around the tank. Previous corrective action not completed.			

Inspector Name: COSTA, RYAN

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).	Date:	06/03/2021
--------------------	--	-------	------------

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690203411	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5861594">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5861594</a>